

**West Valley Middle School
West Valley School District
Yakima, WA**

Total Score = 81% or "Fair"

Date Scored: August 27, 2018

Scorer: Dr. Jerry Gee

	Program Space Needed?	Assigned Rating	Comment Areas							Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other		
Exterior										
Pedestrian Circulation	Y	Fair		x						Students who are dropped off in the parking lot at the side of the building must cross through the bus drop off lane to access the main student entrance.
Vehicle Circulation (incl. service vehicles)	Y	Fair	x						x	Parents dropping off students create a traffic backup for a significant distance on the city streets. Deliveries into the kitchen are proximate to the portable classrooms.
Grounds and Fields	Y	Good								
Parking	Y	Good								
Safety-Security, Signage, Fencing, Etc.	Y	Fair				x				The school lacks security cameras.
Administration										
Administrators	Y	Poor	x	x						The building principal and the lead principal share an office. The office is used as a walkway by staff and students to access the registrar's office.
Reception-Clerical-Business	Y	Good								
Discipline (Security, Detention, ISS, etc.)	Y	Good								
Administrative Support	Y	Fair	x	x	x	x	x	x	x	The school lacks a conference room.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Student Services									
Counselor, SW Offices	Y	Poor	x		x		x	x	The counseling office is undersized and lacks a conference room.
Clinic and Restroom	Y	Fair				x			The nursing area has a sink in the restroom but lacks a sink in the clinic area.
Student Services Support	Y	Poor	x	x	x	x	x	x	The school lacks adequate student service support offices. An itinerant office is set up in the faculty lounge. The braille support individual is located in a storage room.
Staff Support									
Staff Workrooms	Y	Good							
Staff Break Room	Y	Good							
Staff Support and Restrooms	Y	Fair		x					The staff restrooms are located in each pod and can only be accessed by going through a small staff workroom which is often used by the resource room.
Food Services									
Food Preparation	Y	Good							The school has a serve-only kitchen.
Cafeteria	Y	Good							
Dishwashing-Scullery	Y	Good							
Food Storage (Freezer, Cooler, Dry Storage)	Y	Good							
Food Services Support (office, lockers, etc.)	Y	Fair				x		x	The kitchen area lacks a staff restroom and changing area.
Custodial-Maintenance									
Custodial - Maintenance	Y	Poor			x			x	The custodial area lacks a receiving area and adequate storage for supplies and materials.
Restrooms and Corridors	Y	Fair				x			The boys restrooms lack urinal partitions. The school lacks public restrooms other than those found in the office.
General Classrooms	Y	Good							

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Science									
Science Labs	Y	Poor	x		x	x		x	Each pod is equipped with one science room. One of these rooms is being used to teach art. Fifth grade is also utilizing general classrooms for teaching science due to the team teaching approach. Two general classrooms are also being used to teach science in 6th grade.
Science Support	Y	Poor		x	x	x		x	The classrooms that were designed as science rooms have adequate science support facilities. The general classrooms lack science support features.
Special Needs									
Special Education - Resource	Y	Good							
Special Education - Cognitive	Y	Fair	x		x	x	x		The room is undersized and lacks adequate storage for equipment and materials. It lacks natural lighting.
Special Education - Behavior	Y	Poor	x		x	x	x	x	The room is not equipped with a restroom. It is undersized and lacks adequate storage for supplies and materials. It lacks natural lighting. The room lacks individual study carousels.
Title I	N								
Psychologist/SLP	Y	Fair		x				x	The school psychologist is in a small office that lacks natural lighting. It is separated by a folding partition from the behavioral timeout room. Noise between the two spaces can be a significant issue.
Special Needs Support	Y	Fair	x	x	x	x	x	x	The braille support staff member has an office in a storage room. The school lacks adequate office space for special needs support personnel.
Physical Education									
Gymnasium/Multipurpose	Y	Fair				x	x		The gymnasium is undersized with poor lighting.
Weight Room	N								
Lockers	Y	Good							
Physical Education Support	Y	Good							

	Program Space Needed?	Assigned Rating	Comment Areas						Comments	
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other		
Performing Arts										
Music - Instrumental	Y	Fair	x					x	x	The band room is undersized and lacks adequate electrical outlets for technology equipment. It lacks natural lighting.
Music - Vocal	Y	Fair	x		x			x		The vocal room is undersized with poor lighting. It lacks adequate storage for risers and other equipment.
Music Support	Y	Good								
Drama - Stage	Y	Unsatisfactory	x	x	x	x	x	x	x	The school lacks a stage area. Performances are done on the gymnasium floor.
Auditorium	Y	Fair				x	x			The gymnasium is used for school performances. It lacks specialized lighting and acoustical treatments.
Drama Support	Y	Unsatisfactory	x	x	x	x	x	x	x	The school lacks drama support spaces such as a dressing room or greenroom.
Library - Media										
Library	Y	Fair	x		x				x	The library is also used for textbook storage and is used to accommodate some of the animation stations for the STEM program.
Library - Meeting, Conference	Y	Fair	x			x				The instructional area in the library is undersized.
Library Support	Y	Fair	x		x				x	Part of the library support space has been converted to an area to maintain and manage the Chromebook computers.
Computer Labs										
Computer Labs	Y	Good								Each student is equipped with a Chromebook computer. The computer lab is not used on a regular basis.
Computer Lab Support (MDF, IDF, etc.)	Y	Unsatisfactory	x	x	x	x	x	x	x	A portion of the media center support spaces have been converted into a technology support area for Chromebook computers.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
Visual Arts									
Art-2D/3D	Y	Poor	x	x	x	x		x	One science room is used as the art room. The room is equipped with seven small sinks. It lacks adequate storage for art supplies and materials. The school lacks a kiln. The commons area has an art space for each of the pods; however, these spaces are currently utilized for storage and/or small group and individualized instruction.
Art - Computer Graphic	N								
Art Support	Y	Unsatisfactory	x	x	x	x	x	x	A room that was originally designed to teach science is used as the art room. It art art support features.
Career Technical Education									
Introduction to Technology	Y	Good							The room lacks natural light.
Introduction to Technology Support	Y	Good							
Family Consumer Science	N								
Family Consumer Science Support	N								
Business	N								
Business Support	N								
Woods and Crafts	N								
Woods and Crafts Support	N								
Other	Y	Poor	x		x				STEM instruction occurs in a general classroom. It is undersized, requiring some STEM equipment to be housed in the library. The room lacks adequate storage for supplies and materials.
Gifted Education									
	N								