

**Mountainview Elementary School  
West Valley School District  
Yakima, WA**

Total Score = 62% or "Poor"

Date Scored: August 14, 2018

Scorer: Dr. Jerry Gee

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
<b>Exterior</b>									
Pedestrian Circulation	Y	Good							
Vehicle Circulation (incl. service vehicles)	Y	Poor	x	x				x	Parents drop off and pick up students in a small gravel area at the side of the building. Cars often line up a significant distance on the main road in front of the school. Buses load and unload directly in front of the building and all vehicles exit the same location.
Grounds and Fields	Y	Fair				x	x		The school lacks ADA compliant playground equipment.
Parking	Y	Fair						x	The school lacks identified visitor parking.
Safety-Security, Signage, Fencing, Etc.	Y	Fair				x			The intercom system is difficult to hear in some of the classrooms, the music room, the gymnasium, and on the playground.
<b>Administration</b>									
Administrators	Y	Poor	x	x	x			x	The principal's office is located off the hallway that is also used as the faculty work room. Confidentiality can be an issue. The school lacks a conference room. There is inadequate built-in storage for supplies and materials.
Reception-Clerical-Business	Y	Poor	x		x			x	The reception/clerical area is undersized and lacks adequate storage.
Discipline (Security, Detention, ISS, etc.)	Y	Good							
Administrative Support	Y	Unsatisfactory	x	x	x	x	x	x	The school lacks additional administrative support facilities.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
<b>Student Services</b>									
Counselor, SW Offices	Y	Poor	x		x		x		The counselor's office is undersized and is shared with the school psychologist. It lacks adequate storage, natural lighting, a conference room, and a reception area.
Clinic and Restroom	Y	Poor		x	x	x		x	The clinic contains two cots. It does not have a sink or restroom. It lacks adequate storage for supplies and materials. The way it's configured makes direct line-of-sight supervision difficult for clerical staff.
Student Services Support	Y	Unsatisfactory	x	x	x	x	x	x	The school lacks adequate student service support facilities.
<b>Staff Support</b>									
Staff Workrooms	Y	Poor	x	x	x	x	x	x	The work room is in the hallway adjacent to the principal's office. It is long and narrow and lacks adequate storage. It is undersized and is not proximate to any of the classrooms.
Staff Lounge	Y	Fair	x			x			The staff lounge is undersized and is not equipped with staff restrooms
Staff Restrooms	Y	Poor	x			x			The school has one set of staff restrooms. They are located by the gymnasium.
Staff Support	Y	Poor		x	x			x	The school has one office located in the Annex that is used by itinerant staff.
<b>Food Services</b>									
Food Preparation	Y	Good							
Cafeteria	Y	Unsatisfactory	x	x	x	x	x	x	The school lacks a cafeteria. Students eat in their classrooms.
Dishwashing-Scullery	Y	Good							
Food Storage (Freezer, Cooler, Dry Storage)	Y	Good							
Food Services Support	Y	Poor	x	x	x	x	x	x	The kitchen area is not equipped with a restroom, changing area, or an office area.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
<b>Custodial-Maintenance</b>									
Custodial/Maintenance	Y	Poor		x		x			The custodial closets are equipped with wall mounted sinks. None of the portables have any type of storage for custodians.
Restrooms and Corridors	Y	Poor	x			x		x	The student restrooms have a one-way traffic pattern and lack adequate fixtures. The portables are not equipped with restrooms.
Custodial-Maintenance Support	Y	Fair		x	x			x	The custodians lack adequate storage. The portables have no custodial closets..
<b>General Classrooms</b>									
General Classrooms	Y	Fair		x		x		x	Many of the classrooms have a post in the back of the room making configuration difficult. Many of the rooms utilize exposed low-voltage wiring on the ceiling to hook up the ceiling mounted projectors. The Annex building utilizes exterior hallways.
<b>Early Childhood/Kindergarten</b>									
Early Childhood Classrooms	Y	Poor	x	x	x	x	x	x	The ECE rooms are lack student restrooms and adequate storage for large equipment and materials. The preschool is housed on the stage. It is undersized and lacks natural lighting, built-in storage, and a restroom. It is not a conducive space for preschool education.
Early Childhood Support	Y	Unsatisfactory	x	x	x	x	x	x	The school lacks early childhood support facilities.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
<b>Special Needs</b>									
Special Education - Resource	Y	Unsatisfactory	x	x	x	x	x	x	The resource room is located in a portable.
Special Education - Cognitive	Y	Poor	x	x	x	x		x	The self-contained special education classroom is undersized. It is not equipped with a changing table or restroom. It lacks a sensory area. It lacks individualized student work areas.
Special Education - Behavior	Y	Poor	x	x	x	x	x	x	The self-contained special education classroom is undersized. It is not equipped with a changing table or restroom. It lacks a sensory area. It lacks individualized student work areas.
Title I	Y	Good							
Speech Therapy	Y	Fair	x		x				The speech therapist is in a small office that lacks natural lighting.
Psychologist	Y	Fair	x		x			x	The psychologist shares an office with the counselor. The office is undersized, lacks adequate built-in storage, and lacks natural light.
Special Needs Support	Y	Unsatisfactory	x	x	x	x	x	x	The school lacks additional spaces that are designed for special needs support staff. Itinerant staff use the library, classrooms, or other spaces that may be available.
<b>Physical Education</b>									
Gymnasium/Multipurpose	Y	Good							
Physical Education Support	Y	Good							
<b>Music</b>									
Music	Y	Unsatisfactory	x	x	x	x	x	x	Music is taught in a portable.
Music Support	Y	Unsatisfactory	x	x	x	x	x	x	Music is taught in a portable.

	Program Space Needed?	Assigned Rating	Comment Areas						Comments
			Size	Adjacency	Storage	Fixed Equip.	Lighting, IAQ, Acoustics	Other	
<b>Library - Media</b>									
Library	Y	Good							
Library Support	Y	Fair	x		x				The library lacks adequate storage for supplies and materials. The workroom is undersized. The librarian lacks an office.
<b>Computer Labs</b>									
Computer Lab(s)	Y	Fair	x						The computer lab is undersized and lacks natural lighting.
Computer Lab Support	Y	Poor	x	x	x	x	x	x	The school lacks dedicated spaces for technology support and the storage of technology equipment.
<b>Visual Arts</b>									
Art	N								
Art Support	N								
<b>Science</b>									
Science Room	N								
Science Room Support	N								
<b>Performance</b>									
Stage	Y	Poor	x		x	x	x	x	The school has an area that is separated by a curtain from the main gymnasium that is used as the preschool classroom. For school performances, risers are set up in the main gymnasium. The school lacks an elevated stage.
Auditorium	Y	Fair			x	x	x		The gymnasium is used for school programs. It lacks acoustical treatments and specialized lighting. It lacks adequate storage for chairs other than on the stage area.
Stage-Auditorium Support	Y	Unsatisfactory	x	x	x	x	x	x	The school lacks stage-auditorium support facilities.
<b>Gifted Education</b>									
	N								